



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

### Minerals Regulatory Program

May 22, 2008

Reviewed LK

<b>Mine Name:</b> Dugway Pass	<b>Permit Number:</b> S0230091
<b>Operator Name:</b> Davies, Wingle & Davies, Inc.	<b>Inspection Date:</b> May 14, 2008
<b>Inspector(s):</b> L Heppler	<b>Time:</b> 5:00 pm
<b>Other Participants:</b> None	<b>Mine Status:</b> Act

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Bond Renewal Date:** None listed **Bond Amount:** \$18,750

**Purpose of Inspection:** This was a routine annual inspection

**Inspection Summary:** No additional ground disturbance was noted on the site since he last inspection (10-24-07). The site was visited and the disturbance was limited to a road and trench at the end of the road. The actual trench area needs some site clean up as junk (lights, pipe, litter) was scattered about. There is now a small winkie type drill rig located in the trench and a grizzly screen located on site. There was a pop-up camper and drilling mud located further down the road.

Photos were taken to document site conditions.

**Conclusions and Recommendations:** Continue to monitor this site when in the area. The operator needs to maintain a clean site when not mining as well as saving topsoil from areas disturbed to replace when mining is done.

**Inspector's Signature** L Heppler

LAH:pb

cc: Roger Davies

Will Stokes - SITLA

Attach - GIS

O:\M023-Juab\S0230091-Dugwaypass\inspections\Insp\_DugwayPass\_05-14-08.doc

0001



Inspection Date: May 14, 2008  
Page 2 of 2  
S/023/0091

Photos Taken 05-14-08

